

STRING FOR CENTERING

• SQUARE STAVE •

• ROUGHED-OUT STAVE •

• ϕ OF BOW • (A)

36"

30"

24"



18"

12"

6"

• VIEW OF BACK OF STAVE •

• THE FINISHED BOW •



TYPICAL CROSS SECTIONS

REFER TO TABLES OF TYPICAL DIMENSIONS WHEN WORKING STAVE TO PROPER CROSS SECTIONS.

• ϕ OF BOW •


• ALUMINUM TIPS •

• STAG HORN TIPS •

• COW HORN TIPS •


PLATE 2

• MAKING A LEMONWOOD •
• LONG BOW •




OSAGE ORANGE BOW-STAVE

ROUGHED OUT STAVE



BACK VIEW OF BOW

TYPICAL CROSS SECTIONS



LEATHER

SIDE VIEW OF HANDLE





PLATE 5

MAKING A FLAT OSAGE ORANGE BOW